

Factor affecting drying -

- I. Temperature.
- II. Velocity of air
- III. Surface area
- IV. Size of product.
- V. Relative humidity of air.
- VI. Atmospheric pressure and vacume.