

Ans (3) factors affecting Evaporation

- ① Temperature \rightarrow higher temp greater Evaporation
- ② Vapour pressure \rightarrow lower the pressure greater will be the Evaporation
- ③ Surface Area \rightarrow greater the Surface Area greater the Evaporation
- ④ Time \rightarrow longer the time, more is the Evaporation
- ⑤ Concentration \rightarrow low the Concⁿ, greater the Evaporation