

Ans-3 Screening is a method of separate particles according to size.

There are six types of screening equipment-

- 1) Gyration in horizontal plane.
- 2) Gyration in vertical plane.
- 3) Gyration at one & shaking at other.
- 4) Shaking
- 5) Mechanically vibrated
- 6) Electrically vibrated

Ans-4 Causes of solid waste pollution are pollutants from house holds Industrial units, manufacturing units, commercial establishment, landfill units, commercial establishments, landfill, hospital & medical Clinics, trash Collected from household often takes the form of plastic bags & organic wastes.