

(Current - Voltage) (V-I)

THREE (V-I) characteristics used in arc welding DC machines to help control fluctuating currents.

(a) Drooping arc voltage or constant current

(b) Constant arc voltage

(c) Raising arc voltage

In rising voltage characteristic, as the current increases, voltage also increases. Fully welding process uses rising voltage characteristic machine.

