


Histogram

A histogram is drawn by displaying the distribution of data by bar representing marks over

Histogram


A histogram is drawn by displaying the distribution of data by bar graphically the number of units of defective machines over a year

Class Marks	Frequency
10-20	2
20-30	5
30-40	4
40-50	10
50-60	5
60-70	11
70-80	5
80-90	2




Pareto Analysis →

The vital few are on the left, and the trivial many are on the right. In this Pareto diagram WAVE construction for both frequency and dollar.



Coating machine



Coating machine