

and calibrant sales statistics,

3. An inspector must be able to understand both the specifications and the engineering drawings related to the product meets the expected standards. While the inspection may start with a general examination, this also means a quality inspector must be able to measure the product using a variety of hand tools, including torque wrenches, rulers, calipers, gauges and micrometers. The quality inspector may weigh the product if necessary and occasionally destroy the product to determine their limits of abuse it can sustain.