

1. Bending - To force from a straight form into a curved or from a curved form into some different form to bend an iron rod into a hoop. To direct or turn into a particular direction.

Forming - Forming is a process in which the shape of a partly finished product, for example sheet metal is changed using plastic deformation.

Piercing - Piercing is a shearing process where a punch and die are used to create a hole in sheet metal.

Punch - Punch is a forming process that uses a punch press to force a tool called a punch.

Die - A die is a specialized tool used in manufacturing industries to cut material mostly using a press.



Discontinuous - A process that is discontinuous happens in stages with intervals between them, rather than continuously.