

Q2.5 Explain quality control tools.

The quality control tools are the Any chart, device, software, strategy, or technique that supports quality management efforts.

there are 7 quality control tools

- 1) stratification
- 2) Histogram
- 3) check sheet
- 4) Cause & effect diagram
- 5) Pareto chart
- 6) scatter diagram
- 7) Control chart.

* Scatter diagram

its pairs of numericals data, with one variable on each axis to look for a relationship between them. If the variables are correlated, the points will fall along a line or curve, the better the correlation, the tighter the points will hug the line.

