

2. Zeroth Law of Thermodynamics means is that temperature is something worth measuring, because it indicates whether heat will move between objects. This will be true regardless of how the objects interact. Even if two objects don't touch heat may still flow between them, such as by radiation (as from a heat lamp). However according to the Zeroth Law of Thermodynamics, if the systems are in thermal equilibrium, no heat flow will take place.

Let A, B and C be three systems. If A and C are in thermal equilibrium, and A and B are in thermal equilibrium then B and C are in thermal equilibrium.

