

SU-5

① Efflorescence is a crystalline deposit on the face of a brick wall. It is common problem in many areas of India, as it is in many countries. The immediate problems raised by its occurrence is that of disfigurement of masonry, and severe debasement of wall is not uncommon. There is, in addition, the possibility of actual damage to masonry from the growth of salt near its surface.